

Heat Lamp Stand Instructions



1. Place rubber foot over end of each leg. **Note: end marked in yellow goes into cap (see below).**



2. Insert top of leg (with yellow mark) into cap. Holes in leg are open to the center of lamp area.



3. Screw metal brackets into legs. Two brackets will fit on the outside of legs and two will fit on the inside of legs. **Note: Make sure to position holes as indicated in photo above.**

